



**Closure to 'Severe Damage of a Pile Group due to Slope Failure' by
D. E. L. Ong, C. F. Leung, Y. K. Chow, and T. G. Ng**

Author

Ong, DEL, Leung, CF, Chow, YK, Ng, TG

Published

2016

Journal Title

Journal of Geotechnical and Geoenvironmental Engineering

Version

Accepted Manuscript (AM)

DOI

[10.1061/\(ASCE\)GT.1943-5606.0001454](https://doi.org/10.1061/(ASCE)GT.1943-5606.0001454)

Downloaded from

<http://hdl.handle.net/10072/375782>

Griffith Research Online

<https://research-repository.griffith.edu.au>

1 **Closure to “Severe Damage of a Pile Group due to Slope Failure” by D.E.L. Ong,**
2 **C.F. Leung, Y.K. Chow and T.G. Ng**

3 DOI:10.1061/(ASCE GT.1943-5606.0001294

4 D.E.L. Ong¹, C.F. Leung², Y.K. Chow³ and T.G. Ng⁴

5 The authors thank the discussor V. Diyaljee, for his interest in their research
6 publication. To recap, this paper examines the pre-failure and post-failure behaviour
7 of an instrumented cast-in-place concrete pile group comprising four 900-mm
8 diameter piles subject to soil movements as a result of a slope failure that occurred
9 during the unexpected early arrival of a rain storm prior to the year-end monsoon. Out
10 of the four piles, two piles were instrumented. The front pile was instrumented with
11 strain gauges only, while the rear pile was instrumented with both strain gauges and
12 in-pile inclinometer. In-soil inclinometer that measured the free-field soil movement
13 was installed about 1.5 m away from the pile group (see Fig. 1). Because the soil slip
14 was not anticipated in the pile design, only nominal 0.5 % steel reinforcement was
15 provided in the piles and this translates to an ultimate bending moment capacity of
16 only 520 kNm. In comparison, the ultimate bending moment capacity for a 1075-mm
17 diameter bored pile with 3 % steel reinforcement used by Chandrasekaran et al.
18 (1999) was about 3000 kNm as additional bending moment due to soil movement had
19 been anticipated.

20

21 ¹Director (Acting), Research Centre for Sustainable Technologies, Faculty of Engineering, Science &
22 Computing, Swinburne University of Technology, Sarawak Campus, 93350 Kuching, Sarawak,
23 Malaysia. E-mail: elong@swinburne.edu.my

24 ²Professor, Centre for Soft Ground Engineering, Dept. of Civil & Environmental Engineering, National
25 University of Singapore, Singapore 117576. E-mail: ceelcf@nus.edu.sg

26 ³Professor, Centre for Soft Ground Engineering, Dept. of Civil & Environmental Engineering, National
27 University of Singapore, Singapore 117576. E-mail: ceechow@nus.edu.sg

28 ⁴Executive Director, GeoEng Consultants (S) Pte Ltd./ Golder Associates (S) Pte Ltd., Singapore
29 329983. E-mail: ngtg@golder.com.sg

30 Diyaljee (2015) recommended that the authors provide further details and
31 clarification on some specific discrete events and their associated construction
32 sequence so that the overall construction methodology and timeline are more
33 accurately represented. The recommendations suggested by Diyaljee are reasonable
34 and appropriate in view that forensic engineering often requires reporting of explicit
35 details during more critical events. Therefore, the detailed information as
36 recommended by Diyaljee (2015) will be provided hereinafter.

37 The key events as shown in Fig. 5 of Ong et al. (2015) will now be further
38 elaborated to reflect the associated discrete events that also took place within the
39 specific construction periods. Immediately, after the occurrence of soil slip on Day 0
40 (Stage 1), canvas sheet was placed over the affected area to prevent further infiltration
41 of rainwater. During Stage 2 construction, the failed slope was reinstated on Day 4 by
42 placing imported sand onto the failed slope surface to stabilize the affected area. From
43 Day 5 to Day 6, a stretch of about 25 m of sheet pile wall was installed at the toe of
44 the failed slope area and its immediate vicinity in an attempt to negate further slope
45 movements. Further excavation of 1 m was carried out uphill and behind the installed
46 sheet pile wall on Day 7, thus exposing the installed cantilever sheet pile wall.
47 Unfortunately, soil movements continued to occur unabatedly as observed by the
48 increasingly tilted cantilever sheet pile wall as shown in Fig. 2 and also as recorded by
49 the adjacent in-soil inclinometer as shown in Fig. 7 of Ong et al. (2015) until Day 62,
50 despite the installation of waling and strutting system on Day 19 to brace the
51 cantilever wall. Fig. 3 shows the improved representation of the construction timeline
52 to reflect more of the discrete construction activities that had taken place in between
53 the successive major events for better clarity.

54 Besides the general comments, Diyaljee (2015) also requested for specific
55 information that could provide valuable insights to develop understanding of the
56 behavior of piles in relation to the type of cracking so as to improve the analysis and
57 design of piles subject to soil movements. These specific comments are described
58 henceforth:

59 1. All the cast-in-place piles within and outside of the boundary of slope
60 excavation were installed before the initial slope failure. However, the
61 localized excavation to expose the pile heads and subsequently casting of the
62 pile caps, was carried out at different times. For example, the strip of pile
63 groups in the western boundary at Gridline 1 with elevation of RL103.20 m
64 (including the instrumented pile group), was the first area to be locally
65 excavated and casted with pile caps. This was followed by the successful
66 capping of the pile groups located along Gridlines 3 and 4 at elevation of
67 RL100.55 m.

68 Finally, when the installed pile groups at Gridlines 2 and the installed
69 single piles between Gridlines 2 and 3, all at elevation of RL98.0 m (to
70 support the proposed underground water tank) were to be exposed during the
71 subsequent excavation works, slope failure occurred overnight (Day 0) due to
72 the unforeseen heavy rain storm. When the slope failure occurred, the
73 excavation depth was 3.5 m as measured from the existing ground level and
74 was just 1.7 m shy of the proposed final excavation level.

75 2. The locations of the piles supporting the underground water storage tank and
76 sheet piles in relation to the boundary of the slope excavation are now re-
77 emphasized in Fig. 1 for greater clarity.

78 3. From Fig. 2, it was indeed noted that further excavation of 1 m uphill of the
79 reinstated slope and behind the installed sheet pile wall did induce additional
80 soil movements as recorded by both the in-pile and in-soil inclinometers
81 located adjacent to the failed slope in Ong et al. (2015).

82 4. The sheet piles were installed on Day 5 and Day 6 at the toe of the failed slope
83 area and its immediate vicinity in an attempt to stabilize the affected area and
84 to minimise further slope movements (see Fig. 2). However, on Day 7 (end of
85 Stage 2), subsequent excavation of 1 m that was carried out uphill and behind
86 the installed sheet pile wall inevitably caused further detrimental soil
87 movements perhaps due to limited mobilization of the remolded shear strength
88 of the failed clay slope in trying to sustain the original slope gradient.

89 5. As addressed in point 1 above, the cast-in-place piles supporting the
90 underground storage tank were installed before the soil slip occurred on Day 0.

91 The authors agree with Diyaljee (2015) that the observational and numerical
92 backanalysis performed herein are indeed useful to develop insights for the proper
93 understanding and appropriate design of pile reinforcement in (a) cast-in-place
94 retaining walls supporting deep basement excavations (Ong et al., 2006, 2009 &
95 2011) and Leung et al., 2006) or walls located adjacent to existing structures and (b)
96 landslide stabilizing passive piles (Chow, 1996 & Mageri et al., 1994). Other
97 geotechnical scenarios where the concept of soil-structure interaction involving the
98 detrimental effect of soil movements can be of relevance include pile-supported
99 bridge abutments (Stewart et al., 1994a & 1994b, Springman, et al., 1991) and
100 possibly riverine infrastructure located in riverbanks subject to large daily tidal
101 fluctuations (Ting & Tan, 1997, Ting, 2004 and Wong et al., 2015), which is being
102 investigated and shall be discussed in future papers.

103 Besides the fundamental understanding of soil-structure interaction, the authors
104 would also like to acknowledge the importance of accurate assessment of the soil
105 undrained shear strength during pile design. Ong et al. (2006) and Leung et al. (2006)
106 have detailed the importance of differentiating the use of pre-excavation or post-
107 excavation undrained shear strength in assessing the effect of soil movement on piles
108 especially when large strain deformations are expected. As in most practical cases, the
109 pre-excavation undrained shear strength values are available only. Therefore, the
110 maximum normalized limiting soil pressure/undrained shear strength ratio, p_y/c_u of 6
111 was used in the backanalysis, based on the recommendation of Leung et al. (2006).

112 The soil limiting pressure, p_y , which is defined as the maximum soil pressure that
113 can act on a pile without causing any further increase in pile bending moment,
114 becomes more important during large strain soil deformations. In this case study, a
115 'soil flow' phenomenon most likely occurred during the slope failure, whereby the
116 soft marine clay would just flow around the instrumented piles once limiting soil
117 pressure had been reached. Another important design parameter worth mentioning is
118 the soil moderation factor applied to the free-field soil movements recorded by the in-
119 soil inclinometer, which was located adjacent the failed slope. Leung et al. (2006) and
120 Ong et al. (2009) suggested a soil moderation factor of 0.7 for the case of a 4-pile
121 group to reflect the phenomenon of soil reinforcing and shadowing effects due to the
122 presence of multiple individual piles within the group.

123 Since the numerical backanalysis in Ong et al. (2015) yields reasonably good
124 agreement with the field measured results that consider the appropriate use of the
125 cracked pile properties, the practical application of the concept of limiting soil
126 pressure based on p_y/c_u ratio of 6 and the appropriate use of soil moderation factor
127 have now been successfully validated by this case study.

128 In conclusion, the reasonably close agreement of backanalysis results can be
129 attributed to the following important contributions:

130 1. The quality workmanship in preparing and connecting all the geotechnical
131 instruments to the data logging unit that involved a lot of painstaking, but
132 worthwhile efforts. Calibrating, commissioning and maintaining the
133 instrumentation system also formed part of the challenges in this study.

134 2. Discipline in maintaining a daily site monitoring log book system and
135 photographic evidences to keep track on the construction sequence and
136 methodology, which formed an indispensable formal record for the forensic
137 engineering endeavour. The discrete construction events as highlighted by
138 Diyaljee (2015) are as important to create a seamless integration of important
139 technical information.

140 3. Fundamental understanding of the key parameters relevant to this study that
141 include the concept of soil limiting pressure, soil moderation factor and
142 progressive cracking of pile that affects its response when subject to soil
143 movements.

144

145 **References**

146 Chandrasekaran, B., Tang, S. K. and Lim, T. L. (1999). "Behaviour of piled
147 foundation subjected to lateral movements due to deep excavation." *Proc.*
148 *Field Measurements in Geomechanics*, Singapore, 197-200.

149 Chow, Y. K. (1996). "Analysis of piles used for slope stabilization." *Int. Journal for*
150 *Numerical and Analytical Methods in Geomechanics*. 20, 635-646.

151 Diyaljee, V. (2015). Discussion of “Severe Damage of a pile group due to slope
152 failure.” *J. Geotech. Geoenviron. Eng.*, DOI: 10.1061/(ASCE)
153 GT.1943.5606.0001294.

154 Maugeri, M., Castelli, F. and Motta, E. (1994). “Analysis of piles in sliding soil.”
155 *Proc. 3rd Int. Conf. on Deep Foundation Practice Incorporating Piletalk*,
156 Singapore, 191-196.

157 Ong, D.E.L., Leung, C.F. and Chow, Y.K. (2006). “Pile behaviour due to excavation-
158 induced soil movement in clay: I: Stable wall”. *J. Geotech. Geoenviron. Eng.*,
159 132(1), 36-44.

160 Leung, C.F., Ong, D.E.L. and Chow, Y.K. (2006). “Pile behaviour due to excavation-
161 induced soil movement in clay: II: Collapsed wall”. *J. Geotech. Geoenviron.*
162 *Eng.*, 132(1), 45-53.

163 Ong, D.E.L., Leung, C.F. and Chow, Y.K. (2009). “Behaviour of Pile Groups Subject
164 to Excavation-Induced Soil Movement in Very Soft Clay”. *J. Geotech.*
165 *Geoenviron. Eng.*, 135(10), 1462-1474.

166 Ong, D.E.L., Leung, C.F. and Chow, Y.K. (2011). “Behaviour of Pile Groups Subject
167 to Excavation-Induced Soil Movement in Very Soft Clay”. Discussion by F.
168 Castelli & Closure, *J. Geotech. Geoenviron. Eng.*, 137(1), 110-113.

169 Ong, D.E.L., Leung, C.F., Chow, Y.K. and Ng. T.G. (2015). “Severe Damage of a
170 Pile Group Due to Slope Failure”. *J. Geotech. Geoenviron. Eng.*, 141(5),
171 04015014, D.O.I. 10.1061/(ASCE)GT.1943-5606.0001294

172 Springman, S. M., Bolton, M. D. and Randolph, M. F. (1991). “Modeling the
173 behaviour of piles subjected to surcharge loading.” *Proc. Int. Conf. Centrifuge*
174 *91*, Colorado, 253-260.

- 175 Stewart, D. P., Jewell, R. J. and Randolph, M. F. (1994a). "Design of piled bridge
176 abutments on soft clay for loading from lateral soil movements."
177 *Geotechnique*, 44(2), 277-296.
- 178 Stewart, D. P., Jewell, R. J. and Randolph, M. F. (1994b). "Centrifuge modeling of
179 piled bridge abutments on soft ground." *Soils and Foundations*, 32(1), 41-51.
- 180 Ting, W. H. and Tan Y. K. (1997). "The movement of a wharf structure subject to
181 fluctuation of water level". *Proc. XIV Int. Conf. on Soil Mechanics &*
182 *Foundation Engineering, Hamburg*, 903-906.
- 183 Ting W. H. (2004). "Lateral response of piles to soil movement when embedded in
184 banks of limiting stability". *Prof. Chin Fung Kee Memorial Lecture, Proc.*
185 *15th SEAGC*, Bangkok.
- 186 Wong, S.T.Y., Ong, D.E.L. & Leung, C.F. (2015). "Centrifuge model study of single
187 pile subjected to tidal fluctuation and riverbank soil movement". Accepted.
188 *Int. Conf. on Soft Ground Engineering (ICSGE2015)*, Singapore.

Fig 1




Fig 2



Fig 3

Stage	Day	Key Event	Construction Sequence
1	Day 0	<ul style="list-style-type: none"> Soil slip occurred Excavation depth at 3.5 m 	
2	Days 1-7	<ul style="list-style-type: none"> Day 4: Reinstatement of failed slope Days 5-6: Sheet pile installation Day 7: Further excavation to 4.5m depth Further soil movement occurred 	
3	Days 8-14	<ul style="list-style-type: none"> Localized excavation to expose installed pile (heads) supporting underground storage tank 	
4	Days 15-18	<ul style="list-style-type: none"> Further excavation to 5.0m depth 	
5	Days 19-21	<ul style="list-style-type: none"> Days 19-20: Temporary waling & strutting system installed Day 21: Further excavation to 5.5m depth 	
6	Days 22-29	<ul style="list-style-type: none"> Further excavation to 6.0m depth 	
7	Days 30-62	<ul style="list-style-type: none"> Casting of pile caps & further works 	
8	Day 63	<ul style="list-style-type: none"> Backfilling works 	

LIST OF FIGURES

Fig. 1. Plan view showing the locations of instruments, instrumented pile group and piles supporting the underground storage water tank at the site

Fig. 2. Sheet piles installed on Days 5 & 6 at toe of the failed slope and subsequently tilted

Fig. 3. Timeline and details of excavation works